

FUEL OIL DISTRIBUTOR INSPECTIONS

ABOVEGROUND TANKS ☐ INSIDE ☒ OUTSIDE

REPORT NUMBER:

C-31795

NOTE: Inspection is limited to external observation of tanks and components in their operating position.

	1 ST TANK	2 ND TANK
Type of Tank i.e. ULC-S602	500 Gallon 12 Gauge Double welded	
Manufacturer	GRANBY	
Date of Manufacture or Age in Years	MAY 2012	
Serial No.	AA 327405	
1. Is the tank approved for its present use?	☒ Yes ☐ No	☐ Yes ☐ No
2. Does the tank appear to have been installed in accordance with the fuel oil code, the certification document and the manufacturer's instructions?	☒ Yes ☐ No	☐ Yes ☐ No
3. Are the tank vent and fill pipes properly installed and terminated?	☒ Yes ☐ No	☐ Yes ☐ No
4. Is the tank equipped with a proper fill cap?	☒ Yes ☐ No	☐ Yes ☐ No
5. Is the tank equipped with a proper gauge and overfill protection device (whistle)?	☒ Yes ☐ No	☐ Yes ☐ No
6. Is the tank properly supported on a firm base?	☒ Yes ☐ No	☐ Yes ☐ No
7. Is the tank support system in good condition, non-combustible and stable?	☒ Yes ☐ No	☐ Yes ☐ No
8. If two tanks are joined, are they installed on a common slab?	☐ Yes ☐ No ☒ N/A	☐ Yes ☐ No ☐ N/A
9. If two tanks are bottom connected, are they connected with 2 in. pipe?	☐ Yes ☐ No ☒ N/A	☐ Yes ☐ No ☐ N/A
10. Is the system free of leaks or any signs of weepage?	☒ Yes ☐ No	☐ Yes ☐ No
11. Is the tank and piping painted or coated to prevent external corrosion?	☒ Yes ☐ No	☐ Yes ☐ No
12. Are burner supply/return lines free of compression fittings?	☒ Yes ☐ No	☐ Yes ☐ No
13. Are burner supply/return lines installed above grade and protected or underground and chased?	☒ Yes ☐ No	☐ Yes ☐ No
14. Are burner supply/return lines installed to code?	☒ Yes ☐ No	☐ Yes ☐ No
15. Is an approved shut-off valve installed?	☒ Yes ☐ No	☐ Yes ☐ No
16. Is an approved filter installed?	☒ Yes ☐ No	☐ Yes ☐ No
17. Is the fill/vent pipe steel or galvanized construction?	☒ Yes ☐ No	☐ Yes ☐ No
18. Is the tank located at least 2 feet from the appliance or is the tank protected from the appliance by a fire rated wall. (for inside tank only)	☐ Yes ☐ No ☒ N/A	☐ Yes ☐ No ☐ N/A
19. If required is the tank protected from vehicle damage?	☐ Yes ☐ No ☒ N/A	☐ Yes ☐ No ☐ N/A
20. If required is the tank (over 2500L) protected with appropriate secondary containment?	☐ Yes ☐ No ☒ N/A	☐ Yes ☐ No ☐ N/A
NOTES: (any "No" answers must be explained in this section and the affected equipment repaired, replaced or tagged.)		

COMMENTS:

Contractors Name (Please Print Clearly)

Kevin's Oil Burner Service

TSSA #

000076638113

Technician's Name (please print clearly):

Kevin Becher

Telephone:

209-282-7888

Technician's Signature:

Kevin Becher

Certificate No.:

0702776

Date:

April 6/21

OW NELS
CWP 123

FUEL OIL DISTRIBUTOR INSPECTIONS APPLIANCES - COMPREHENSIVE

REPORT NUMBER:

C-31795

OWNER / OPERATOR:

Gus VANBAARSE

LOCATION:

41 AUMSVILLE RD

TELEPHONE NO.

705 781-7226

OWNER'S ADDRESS (If different from above):

(House)

(SHOP)

Type of Appliance	1 st APPLIANCE	2 nd APPLIANCE
Manufacturer	FORCED AIR OIL OLSEN	FORCED AIR OIL BROCK
Model	BCL 115	FBR-1
Date of Manufacture or Age in Years	N/A	1984
Size (BTU/Hr)	117,000	112,000
Serial No.	V-937	H83
1. Is the appliance approved?	☒ Yes ☐ No	☒ Yes ☐ No
2. Is the appliance installed in accordance with the fuel oil code?	☒ Yes ☐ No	☒ Yes ☐ No
3. Is the appliance being used in accordance with its approval?	☒ Yes ☐ No	☒ Yes ☐ No
4. Is the appliance venting installed in accordance with the fuel oil code?	☒ Yes ☐ No	☒ Yes ☐ No
5. Is the venting system free of defects, debris or corrosion	☒ Yes ☐ No	☒ Yes ☐ No
6. Is the vent sized properly?	☒ Yes ☐ No	☒ Yes ☐ No
7. Is proper combustion and ventilation air openings installed?	☐ Yes ☐ No ☒ N/A	☐ Yes ☐ No ☒ N/A
8. Is the installation free of indications of heat exchanger cracks, defects in the refractory, pot and/or heat shields?	☒ Yes ☐ No	☒ Yes ☐ No
9. Are all limits and safety controls properly installed?	☒ Yes ☐ No	☒ Yes ☐ No
10. Is the appliance installed with appropriate clearances from combustibles?	☒ Yes ☐ No	☒ Yes ☐ No
11. Are the results of combustion analysis acceptable?	☒ Yes ☐ No	☒ Yes ☐ No
12. If required, is there a proper chimney cleanout?	☒ Yes ☐ No ☐ N/A	☒ Yes ☐ No ☐ N/A
13. Is the chimney properly lined?	☒ Yes ☐ No ☐ N/A	☒ Yes ☐ No ☐ N/A
14. Is the vent liner fitted with proper flashing, cap and base T?	☐ Yes ☐ No ☒ N/A	☐ Yes ☐ No ☒ N/A
15. If there is a sidewall vent attached to the appliance is it installed according to code and the manufacturer's instructions?	☐ Yes ☐ No ☒ N/A	☐ Yes ☐ No ☒ N/A
NOTES: (any "No" answers must be explained in this section and the affected equipment repaired, replaced or tagged).		
COMMENTS:		

Technician's Signature:

K. Beckel

Certificate No.:

0702776

Date:

Aug 6/21

OW NICKS
CUP 125

FUEL OIL DISTRIBUTOR INSPECTIONS APPLIANCES - COMPREHENSIVE

REPORT NUMBER:

C-31795

OWNER / OPERATOR:

GUS VANBAARSEL

LOCATION:

41 AUENSVILLE RD

TELEPHONE NO.

705 281-7226

OWNER'S ADDRESS (If different from above):

Type of Appliance	(HOUSE) 1 ST . APPLIANCE	(SHOP) 2 ND . APPLIANCE
Manufacturer	FORCED AIR OIL	FORCED AIR OIL
Model	OLSEN	BROCK
Date of Manufacture or Age in Years	BCL 115	FBR-1
Size (BTU/Hr)	N/A	1984
Serial No.	117,000 V-937	112,000 H83
1. Is the appliance approved?	☒ Yes ☐ No	☒ Yes ☐ No
2. Is the appliance installed in accordance with the fuel oil code?	☒ Yes ☐ No	☒ Yes ☐ No
3. Is the appliance being used in accordance with its approval?	☒ Yes ☐ No	☒ Yes ☐ No
4. Is the appliance venting installed in accordance with the fuel oil code?	☒ Yes ☐ No	☒ Yes ☐ No
5. Is the venting system free of defects, debris or corrosion	☒ Yes ☐ No	☒ Yes ☐ No
6. Is the vent sized properly?	☒ Yes ☐ No	☒ Yes ☐ No
7. Is proper combustion and ventilation air openings installed?	☐ Yes ☐ No ☒ N/A	☐ Yes ☐ No ☒ N/A
8. Is the installation free of indications of heat exchanger cracks, defects in the refractory, pot and/or heat shields?	☒ Yes ☐ No	☒ Yes ☐ No
9. Are all limits and safety controls properly installed?	☒ Yes ☐ No	☒ Yes ☐ No
10. Is the appliance installed with appropriate clearances from combustibles?	☒ Yes ☐ No	☒ Yes ☐ No
11. Are the results of combustion analysis acceptable?	☒ Yes ☐ No	☒ Yes ☐ No
12. If required, is there a proper chimney cleanout?	☒ Yes ☐ No ☐ N/A	☒ Yes ☐ No ☐ N/A
13. Is the chimney properly lined?	☒ Yes ☐ No ☐ N/A	☒ Yes ☐ No ☐ N/A
14. Is the vent liner fitted with proper flashing, cap and base T?	☐ Yes ☐ No ☒ N/A	☐ Yes ☐ No ☒ N/A
15. If there is a sidewall vent attached to the appliance is it installed according to code and the manufacturer's instructions?	☐ Yes ☐ No ☒ N/A	☐ Yes ☐ No ☒ N/A
NOTES: (any "No" answers must be explained in this section and the affected equipment repaired, replaced or tagged).		
COMMENTS:		

Technician's Signature:

Ki Becker

Certificate No.:

0702776

Date:

Aug 6/21