


NORTH BAY-MATTAWA CONSERVATION AUTHORITY



NOTICE OF COMPLETION

PERMIT #: 31/PE/08

OWNER:		TEL.:	
--------	--	-------	--

LOT LOCATION (Civic #):	<u>105 B New Lake Road</u>		
LEGAL DESCRIPTION: (Lot, Concession, Sublot(s), Plan(s), Parcel(s))	<u>Pt Lot 15, Con 12; Pt 1 Plan 42R-13506</u>		
TOWNSHIP:	<u>Perry</u>	DISTRICT:	<u>Perry Sound</u>
ROLL NUMBER:	<u>49-14-000-003-311-30-0000</u>		

SUBSTANTIAL COMPLETION OF INSTALLATION	INSPECTION DATE:	INSPECTOR:
	<u>Aug 18/08</u> <u>A. Pette</u> REMARKS: <u>installed as per OBC.</u>	

SITE EVALUATION COMPLETION	INSPECTION DATE:	INSPECTOR:
	<ul style="list-style-type: none"> Side Slopes 60% Vegetative Growth <u>Oct 27/08</u> <u>A. Pette</u> REMARKS: <u>bed fully covered w shallow rooted vegetation.</u>	

DWELLING INFORMATION	BEDROOMS	FLOOR AREA	FIXTURE UNITS	NATIVE SOIL T-TIME
	<u>4</u>	<u>120.4m²</u>	<u>18</u>	<u>10</u>


CLASS OF SYSTEM	SIDEWALL AREA	TANK SIZE	BED SIZE	CONTACT AREA	MANTLE LOAD AREA
2 3 4 <u>4F</u> 5		<u>4500L</u>	<u>29.25m²</u>	<u>29.25m²</u>	<u>Existing</u>

CLASS OF SYSTEM	TANK SIZE	BED SIZE	STONE AREA	SAND AREA
OTHER:				

SEWAGE SYSTEM NOTICE OF COMPLETION

Pursuant to the requirements of Sections 8.-(1) and 11.-(1) of the Building Code Act, you are hereby informed that the above construction has been completed in accordance with the permit documents and the Ontario Building Code, DivB Part 8.

DATE:	<u>10/29/08</u>	I/CBO-SS:	
-------	-----------------	-----------	--



THIS WORK IS AUTHORIZED SEWAGE SYSTEM PERMIT

Permit #: 31/PE/08

This Permit MUST be Posted Onsite Prior to Construction

District: Pawy Sound Twp: Perry Legal Desc: Pl. lot 15, Con. 12, Part 1 on Plan

Property Owner: [Redacted] Civic Address: 105 Deer Lk. Rd. 42R13506

MANDATORY INSPECTIONS

Preliminary Site Evaluation

Test pits must be excavated in the proposed location of the sewage system (min. 1.5metres in depth)

Substantial Completion of Installation

Current Filter Graphs must be submitted to the NBMCA prior to scheduling a substantial completion inspection

The following must be **FULLY EXPOSED** prior to inspection

- Tanks
- Distribution Box
- All Distribution Pipes Exposed
- Any/All increased contact area
- Geotextile or untreated building paper on site
- Pumps, pump chamber and alarms installed and operational

Final Completion Inspection

Grading of side slopes, mantle complete – topsoil and shallow rooted vegetation covering a minimum 60% of system including the mantle

Failure to request mandatory inspections may be subject to penalties

THIS WORK IS AUTHORIZED FOR THE:

CONSTRUCTION OF AN ON-SITE SEWAGE SYSTEM

- NEW CONSTRUCTION REPLACEMENT / ALTERATION
- DEMOLITION OF AN ON-SITE SEWAGE SYSTEM
- CONDITIONAL PERMIT (see conditions listed below)

Inspected and Recommended by _____

Approved by _____


[Signature]
(ICROSS) / (DPCROSS)
(SSSI)

Sewage System Permit #: 31/PE/08

Dated: 08 / 08 / 2008

PERMIT EXPIRATION DATE: 08 / 08 / 2009

NORTH BAY-MATTAWA CONSERVATION AUTHORITY



TO THE NORTH BAY-MATTAWA CONSERVATION AUTHORITY

Total Number of Bedrooms:	4
Total Floor Area of Buildings:	120.4m ²
Total Fixture Units:	18

DESCRIPTION	Total # of Fixtures
Sinks	4
Toilets	2
Bathtub/Showers	2
Machines	2
Other	0

CLASS 2 – GREYWATER PIT PERMIT #: _____
 Calculated Sidewall Area: _____ m²
 Dimensions of Pit: Length _____ m; Width _____ m; Depth _____ m;

SEPTIC TANK PERMIT #: 31/PE/08
 _____ Using Existing Tank; New CSA Standard Tank
 Volume of Tank: ~~5000~~ Litres 4500 *[Signature]*

TREATMENT UNIT
 Make/Model: _____
 Operating Capacity: _____ Litres/day

CLASS 4 TRENCH BED PERMIT #: _____
 _____ In-Ground Bed; _____ Raised Bed // Raised Height of Bed: _____ m
 _____ Imported Mantle; _____ Existing Mantle // Size of Mantle Required: _____ m²
 Total Length of Pipe: _____ m // Approved for Pump: _____ YES _____ NO


CLASS 4F FILTER BED PERMIT #: 31/PE/08
 In-Ground Bed; _____ Raised Bed // Raised Height of Bed: 0 m
 _____ Imported Mantle; Existing Mantle // Size of Mantle Required: 200 m²
 Filter Bed Area: 27 m² // Size of Contact Area: 27 m² // Approved for Pump: _____ YES NO

CLASS 5 HOLDING TANK PERMIT #: _____
 Size of Tank: _____ Litres; _____ Concrete; _____ Polyethylene; _____ Other (specify) _____


TERTIARY TREATMENT UNIT PERMIT #: _____
 Make/Model: _____ // Flow Rate: _____ L/day
 Raised Height: _____ m // Stone Area: _____ m² // Sand Area: _____ m²

Inspected and Recommended by *[Signature]* / Approved by *[Signature]*
(SSI) (CBO-SS) / (LDCBO-SS)

Dated: 06/08 / 08 / 2008 PERMIT EXPIRATION DATE: 06/08 / 08 / 2009
(day) (month) (year) (day) (month) (year)



105 DEER LK RD.



105 DEER HIK RD